

Client: Albany Memorial Hospital									Date: 3/5/2019		
	•		•	hanı NV	10001				Date: 3/3/20		
			BIVa. AI	bany, NY	12204						
	Larry Tilt Dakota		co Didlyno								
				JIIAN							
Purpose (of visit:	Routine Envir	ox Service								
			Wate	r Analysis a	and Perforr	nance	Indicators				
Envirox	Alarms?	CIO ₂	CIO ₂ DPD	CIO ₂ Probe	CIO ₂ Probe	WM	Water Meter		Gallons of	CIO2 Dosing	
Location		Monitor Reading	Test	Re- calibrated?	Rebuilt?	GPM	Total	Changed?	NaClO ₂ Online?	Pump Settings	
Cold	No	0.43 ppm	0.41 ppm	Yes	No	69	1038390	No	55	66%	
				Operation	nal Systen	n Chec	ks				
	Incoming	After	NaClO ₂	NaClO ₂	Generator	Cassette Voltages (8-35)		Cassette Hours x/x/x/x			
Envirox Location	Water Hardness	Softener Hardness	Pump Primed?	Pump Rebuilt?	internal PSI? (2-10)					Salt in Brine Tank?	
Main	50 ppm	0 ppm	Yes	No	6.5	20.5	/ 22.9	440 / 44	0	Yes	
			Doi	mestic Wate	er System I	Repres	entation				
Location	1st Floor Emergency		2nd Fl Hand Break Rm		4th Floor CCD RM 2		6th Floor Rm 619		6th Floor South Waiting		
Time	12 pm		12:05 pm		12:15 pm		12:40 pm		12:30 pm		
CLO ₂ Test	Cold- 0.24 Hot- ND		Cold- 0.25 Hot- ND		Cold- 0.19 Hot- ND		Cold- 0.02 Hot- ND		Cold- 0.34 Hot- ND		
Odor? Y/N	Hot Chlorite- 0.48 ppm		No		No	No No		Hot Chlori		ite- 0.43 ppm	
					Inventories	3					
Envirox Location	# of Cassettes		Total # of NaClO ₂ gallons	Generator & Monitor Pre- filters	Dosina	up (Lbs)		CIO2 Probe Rebuild Kits	Electrolyte (ml)	Dosing Pump Rebuild Kits	
Main	0 NSF 1	000 60		MAC- 15	6 15		1		N/A	1	
				Gen C- 3							
Final Check	s: Timer set	ting = 0 min/	hr √ Elect	ronic Valve =	55-65% √ Ch	eck for I	eaks √ Feed	water PSI = 3	5-40 √		
Comment				g normally up on flus			luals are lo	w on the	6th floor N	orth Wing	
Parts for 2 NSF 1	next trip: 000 Cass	ettes	Note: CIO2	= (Chlorine Diox	ide). NaCIO2 – ((Sodium-1	Chlorite HYG-24	5. Precursor\			
Techniciar	ղ։ Colin Moss	brucker		_ (5111511116 210)	Signature:		alm Massi	lucker			
	Signature:	L	2	ab				Date: 3/5/20)19		
							_				

Nalco makes no warranties with respect to water system biohazards from waterborne pathogens including but not limited to Legionella bacteria. Nalco does not and cannot make any guarantee or warranty that the risk of the presence of Legionella or the risk of legionellosis has been reduced or eliminated by reason of the Program.