

NALCO SERVICES REPORT



Client: Albany Memorial Hospital

Date: 1-25-2019

Site Address: 600 Northern Blvd. Albany, NY 12204

Attention: Larry Tilton

Copies To: Dakota Snyder, Mike Pidlypchak

Purpose of visit: Routine Envirox Service

Water Analysis and Performance Indicators

Envirox Location	Alarms?	ClO ₂ Monitor Reading	ClO ₂ DPD Test	ClO ₂ Probe Re-calibrated?	ClO ₂ Probe Rebuilt?	WM GPM	Water Meter Total	Prefilters Changed?	Gallons of NaClO ₂ Online?	ClO ₂ Dosing Pump Settings
Main	No	0.56	0.48	No	No	91	9551697	MAC	8.5	66%
								Gen Sed		

Operational System Checks

Envirox Location	Incoming Water Hardness	After Softener Hardness	NaClO ₂ Pump Primed?	NaClO ₂ Pump Rebuilt?	Generator internal PSI? (2-10)	Cassette Voltages (8-35)	Cassette Hours x/x/x/x	Salt in Brine Tank?
Main	50 ppm	0 ppm	Yes	No	6.7	24.7 / 26.8	620 / 620	Yes

Domestic Water System Representation

Location	1st Floor Emergency	2nd Fl Hand Break Rm	4th Floor CCD RM 4	6th Floor Rm 619	6th Floor South Waiting
Time	12:35 pm	12:45 pm	12:55 pm	1:10 pm	1:20 pm
ClO ₂ Test	Hot- ND Cold- 0.27	Hot- ND Cold- 0.37	Hot- ND Cold- 0.15	Ho- ND Cold- 0.27	Hot- ND Cold- 0.46
Odor? Y/N	Hot Chlorite- 0.63 ppm	No	No	No	Hot Chlorite- 0.66 ppm

Inventories

Envirox Location	# of Cassettes	Total # of NaClO ₂ gallons	Generator & Monitor Pre-filters	Dosing Tank Filters	Softener Salt Back-up (Lbs)	ClO ₂ Probe Rebuild Kits	Electrolyte (ml)	Dosing Pump Rebuild Kits
Main	0 NSF 1000	8.5	MAC-16	6	30	1	N/A	1
			Gen C-3					

Final Checks: Timer setting = 0 min/hr ✓ Electronic Valve = 55-65% ✓ Check for leaks ✓ Feedwater PSI = 35-40 ✓

Comments: All equipment operating normally. Expect a delivery of 55 gallon precursor within the next business day. When recieved please put online. 1 low residual on the 4th floor. Keep up on flushing protocols.

Parts for next trip:

Note: ClO₂ = (Chlorine Dioxide), NaClO₂ = (Sodium Chlorite, HYG-25, Precursor)

Technician: Colin Mossbrucker

Signature:

Customer Signature:

Date: 1-25-2019

Nalco makes no warranties with respect to water system biohazards from waterborne pathogens including but not limited to Legionella bacteria. Nalco does not and cannot make any guarantee or warranty that the risk of the presence of Legionella or the risk of legionellosis has been reduced or eliminated by reason of the Program.